



Thermal Network Value Hybrid Speed Dome Camera (SD5X41)

V2.650.0000000.3.R.230411

Release Notes



Legal Information

Copyright

© 2023 ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD. All rights reserved.

This document cannot be copied, transferred, distributed, or saved in any form without the prior written permission of Zhejiang Dahua Vision Technology Co., LTD (hereinafter referred to as "Dahua").

The products described in this document may contain the software that belongs to Dahua or the third party. Without the prior written approval of the corresponding party, any person cannot (including but not limited to) copy, distribute, amend, abstract, reverse compile, decode, reverse engineer, rent, transfer, sublicense the software.

Trademarks

, , , and **HDCVI** are the trademarks or registered trademarks of Dahua.

All other company names and trademarks mentioned herein are the properties of their respective owners.

Disclaimer

- These release notes are for reference only. Slight differences might be found between the release notes and the product.
- Succeeding products and release notes are subject to change without notice.
- If there is any uncertainty or controversy, we reserve the right of final explanation.

Table of Contents

Legal Information	I
Release Notes	1
1.1 Overview	1
1.2 New Features	1
1.3 Fixed Bugs	1
1.4 New Feature Details	1
1.5 Compatibility	1
1.5.1 Program	1
1.5.2 Browser	2
1.5.3 Third Party Access	2
1.6 Software Environment	2
1.7 Pending Issues	2
1.8 Update Guide	2

Release Notes

1.1 Overview

Item	Description
Product model	Thermal Network Value Hybrid Speed Dome Camera (SD5X41)
Version	V2.650.0000000.3
Software package information	DH_TPC-SD5X41-TB-S2_MultiLang_NP_V2.650.0000000.3.R.230411.zip
OS requirement	None
Release date	April 28, 2023

1.2 New Features

None

1.3 Fixed Bugs

Fixed bugs	Description
1	Fixed the issue that the PTZ camera with temperature measurement function stops abnormally.
2	Fixed the issue that the SD card cannot be read under the exfat format.
3	Fixed the issue that the security camera cannot export raw data normally.
4	Fixed the issue that automatic calibration of high temperature occasionally failed.

1.4 New Feature Details

None

1.5 Compatibility

1.5.1 Program

Compatible with the previous version.

1.5.2 Browser

Chrome\IE11.

1.5.3 Third Party Access

- CGI testing tool version: V2.91.1.1
- ONVIF testing tool version: 20.12(V3.1.0.1064635)

1.6 Software Environment

Category	Model	Version
NVR	NVR	V4.002.0000000.1.R.211231
Client	DMSS	<ul style="list-style-type: none">• IOS: 1.97.000• Android: 1.97.000
	IVSS	DH_IVSS7XX_Chn_V2.004.0000000.0.R.211021
	ICC	V5.000.0000008.5.R
Platform	DSS pro	V8.000.0000004.0.R.20211104

1.7 Pending Issues

None.

1.8 Update Guide

For update guide, please refer to "5.4 Upgrading Firmware" in *Web Operation Manual*.

ZHEJIANG DAHUA VISION TECHNOLOGY CO., LTD.

Address: No.1199, Bin'an Road, Binjiang District, Hangzhou, P.R. China

Postcode: 310053

Tel: +86-571-87688883

Fax: +86-571-87688815

Email: overseas@dahuatech.com

Website: www.dahuasecurity.com