

The J60 is a conduit junction box complete with lid tamper detection. It provides 8 terminals for wiring, with two reserved for tamper functionality.

INSTALLATION

Open the J60 by removing the lid screw and lifting the lid hinge.

Drill appropriate fitting holes to the surface the junction box will be mounted to. Use screw anchors if the surface requires them.

Wire as appropriate, ensuring the tamper terminals (nickel screws) are connected to the receiving panel for graded installations.

Screw the J60 base to the mounting surface. Insert required conduit connectors to the open ends of the junction box. Ensure all connections are OK.

Close the lid to clamp the conduit connectors and replace the lid screw.

DIAGRAM

