


The J80 is an 8+2 way junction box complete with tamper detection.

INSTALLATION

To install, remove the junction box lid and drill appropriate fitting holes in the mounting surface. Screw the base to the surface.

Connect the central two terminals to a tamper detection circuit. The metal leaves will break contact when the lid is lifted from the unit.

Wire to suit your installation, then replace & screw down the junction box lid.



NOTES

Ensure wiring does not short other connections inside the unit.

Max Voltage = 125V DC / 230V AC

Max Current = 3A