





INSTALLATION & MAINTENANCE MANUAL



LFCxx




1. Peel off the 3M tape from the back of the LED strip




2. Open the connector



3. Insert the LED flex with the chips facing up and the connector facing down. Lock the connector onto the LED flex. Insert LED flex or supply cable into the other side and repeat the process



4. Add the glue into the hole of the connector until it starts to overflow. Wipe away any excess glue



5. Cover the hole with the cap and allow to dry for 10 minutes before handling



ML Accessories Limited LU5 4LT
www.mlaccessories.co.uk